ENNA SID RWY 34 (RNAV) - ROUTES

GENERAL: Surveillance service shall be available

RADIO COMMUNICATION FAILURE:

Squawk A7600. Maintain last assigned LVL for 2 minutes, then climb to CPL cruising LVL. Aircraft under vectoring shall, after set transponder to A 7600, proceed in the most direct manner possible to rejoin the CPL route no later than the next significant point, climbing to the CPL cruising LVL taking into consideration the applicable MNM flight ALT.

When being vectored or cleared for DCT routing, the climb gradient(s) stated in SID "RESTRICTIONS"-table apply. VECTORING/ DIRECT ROUTING:

ATC CLEARANCE: Departing IFR flights shall obtain ATC clearance from "Banak TWR".

At first contact with "Banak TWR" state "UNABLE RNAV 1 DUE (reason)". OMNI-DIRECTIONAL DEPARTURE available (see ENNA AD 2.24) NON RNAV 1 ACFT:

DESIGNATOR	ROUTE	RESTRICTIONS	CLIMB TO	CONTACT
DONEX 1B	Climb on course 342° to	MNM climb gradient 3.7%	7000 FT	As instructed by Banak
	1900 FT, turn left DCT	(225 FT/NM) to 2400 FT.		TWR.
(DONEX ONE BRAVO	DONEX.		Expect further	
DEPARTURE)		If unable to comply, inform ATC.	climb from ATC	
· ·				

19 MAY 2022 Avinor