ENBO SID RWY 07/25 (RNAV, CAT H) - ROUTES

REMARKS: CAT H

GENERAL: Surveillance service shall be available.

RADIO COMMUNICATION FAILURE:

Squawk A7600. Maintain last assigned LVL for 2 minutes, then climb to CPL cruising LVL. Aircraft under vectoring shall, after set transponder to A 7600, proceed in the most direct manner possible to rejoin the CPL route no later than the next significant point, climbing to the CPL

cruising LVL taking into consideration the applicable MNM flight ALT.

When being vectored or cleared for DCT routing, the climb gradient(s) stated in SID "RESTRICTIONS"-table apply. **VECTORING/ DIRECT ROUTING:**

At first contact with BODØ ATC state "UNABLE RNAV 1 DUE (reason)". OMNI-DIRECTIONAL DEPARTURE available (see ENBO AD 2.24) NON RNAV 1 ACFT:

RWY 07

DESIGNATOR	ROUTE	RESTRICTIONS	CLIMB TO	CONTACT
SENEQ 1E	Climb on course 072° to	MNM climb gradient 6.0% (365	1500 FT	When
	450 FT, turn right to	FT/NM) to 450 FT.		instructed by
(SENEQ ONE ECHO	intercept and proceed on			Bodø TWR,
DEPARTURE)	course 297° to SENEQ.	If unable to comply, inform ATC.		contact Bodø
				DEP 119.705
				MHZ.

RWY 25

DESIGNATOR	ROUTE	RESTRICTIONS	CLIMB TO	CONTACT
SENEQ 1F	Climb on course 252° to 450		1500 FT	When
	FT, turn right to intercept			instructed by
(SENEQ ONE	and proceed on course 297°			Bodø TWR,
FOXTROT	to SENEQ.			contact Bodø
DEPARTURE)				DEP 119.705
· ·				MH7

27 NOV 2025 Avinor