## **ENSO OMNI DIRECTIONAL DEPARTURES RWY 14/32**

RADIO COMMUNICATION FAILURE:

Squawk A7600. Climb on described track to 4000 FT, then proceed in the most direct manner possible to join the CPL route, climbing to CPL cruising LVL. Aircraft under vectoring shall, after setting their transponder to A7600, proceed in the most direct route to join the CPL route, climbing to CPL cruising level.

CLOSE-IN OBSTACLES: Terrain and vegetation 500 m South of THR RWY 32, require more than 5.5% climb gradient, and

must be avoided visually or by other means

When being vectored or cleared for DCT routing, the climb gradient(s) stated in Omni-directional departure "RESTRICTIONS"-table apply. VECTORING/DIRECT ROUTING:

MAGNETIC VARIATION: 2°E (2020)

## **RWY 14**

DESIGNATOR	ROUTE	RESTRICTIONS	CLIMB TO	CONTACT
OMNI-	Climb on track 143°.	MNM climb gradient 5.5% (334	4000 FT.	When instructed by
DIRECTIONAL		FT/NM) to 2500 FT.		Sørstokken Information
DEPARTURE 1A	Expect further clearance			contact Flesland Approach
	from Flesland Approach.	If unable to comply, inform		121.005 MHZ or 126.105
(ENSO1A)		Sørstokken Information.		MHZ.

## RWY 32

1

I

DESIGNATOR	ROUTE	RESTRICTIONS	CLIMB TO	CONTACT
OMNI-	Climb on track 323°.	MNM climb gradient 4.5% (273	4000 FT.	When instructed by
DIRECTIONAL		FT/NM) to 4000 FT.		Sørstokken Information
DEPARTURE 1B	Expect further clearance			contact Flesland Approach
	from Flesland Approach.	If unable to comply, inform		121.005 MHZ or 126.105
(ENSO1B)		Sørstokken Information.		MHZ.

04 SEP 2025 Avinor